
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary ————————————————————————————————————									
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length		
S1028-024	Smoke	8/12/2008	ADS/TM	S09WW_014MH	Dry	Yes	1,215.00		



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary —								
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length	
S1028-024	Smoke	8/12/2008	ADS/TM	S09WW_014MH	Dry	Yes	1,215.00	

Isolated Pipes =

Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S09WW_004MH	S09WW_010MH	301.9108	8
S09WW_014MH	S09WW_004MH	277.6629	8
S09WW_016MH	S11WW_019MH	320.8032	8
S09WW_010MH	S09WW_016MH	314.6188	8
	S09WW_004MH S09WW_014MH S09WW_016MH	S09WW_004MH S09WW_010MH S09WW_014MH S09WW_004MH S09WW_016MH S11WW_019MH	Upstream MH Downstream MH (ft) \$09WW_004MH \$09WW_010MH \$01.9108 \$09WW_014MH \$09WW_004MH 277.6629 \$09WW_016MH \$11WW_019MH \$20.8032

Observations & Photos

Obs_ID S1028-024-OB01

Address 3502 Liberty Heights Ave

Status Private **Source** Cleanout

Location Yard - side **Nearest MH** \$09WW_014MH

Comments Smoke from cleanout in front yard. 3502

Liberty Heights Ave.

Picture \S1028-024-OB01-P01.jpg

Comments Side of house, 3502 Liberty

Heights Ave.

Obs_ID S1028-024-OB02

Address 3316 Liberty Heights Ave

Status Private **Source** Cleanout

Location Yard - front **Nearest MH** S09WW_010MH

Comments Smoke from cleanout in front yard. 3316

Liberty Heights Ave.



Picture \S1028-024-OB02-P01.jpg

Comments Front of house, 3316 Liberty

Heights Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summarv

	,	D-4-			<u> </u>		T-4-1
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-024	Smoke	8/12/2008	ADS/TM	S09WW_014MH	Dry	Yes	1,215.00

Obs_ID S1028-024-OB03

Address 3314 Liberty Heights Ave

Status Private **Source** Cleanout

Location Yard - front **Nearest MH** S09WW_010MH

Comments Smoke from cleanout in front yard. 3314

Liberty Heights Ave.



Picture \S1028-024-OB03-P01.jpg

Comments Front of house, 3314 Liberty

Heights Ave.

Obs_ID S1028-024-OB04

Address 3312 Liberty Heights Ave

Status Private **Source** Cleanout

Location Yard - front **Nearest MH** S09WW_016MH

Comments Smoke from cleanout in front yard. 3312

Liberty Heights Ave.



Picture \S1028-024-OB04-P01.jpg

Comments Front of house, 3312 Liberty

Heights Ave.